



## **Geography**

**Keddington Lock**

**Grid Reference: TF 345 884**

**state of Lock: Very Poor**

**Status: Not Listed**

**Renovation to Date: AWA**



Keddington Lock - 1980



Keddington Lock - Showing Steps and Cill  
March 2006

2010

The winter weather has taken its toll on Keddington Lock degrading the structure badly. Here are some photographs of the damage, kindly supplied by a Trust Member Peter O'Callaghan. The Navigation Trust are looking into how this damage can be minimised and solutions are being looked at.





2019

Fast forward to February 2021

Lindsey Marsh Drainage Board have got the regeneration of Keddington Lock in

hand and doing a brilliant job of repairing the damage shown in the above pictures. It appears that the lock was beyond repair to its original state and is being developed as a weir to control the flow of water in the canal.

Here is a photo of the weir as it is now, but you can keep up to date with pictures of progress on our Facebook page [here](#)

